ARM Manus Research Station

Site Visit 0610M Report

Visit Duration: 11 October to 26 October 2006

Manus Island, Papua New Guinea

SV-0610M Final Report				
Site: Manus Dates on Site: 11-26 October 2006				
Team Members: Troy Culgan John Glowacki	Required Items & Other Actions: • Cal kit • RAID collector w/ 2 RHE OS HDs • Metpack for GPS Suominet • TSI mirror • 2 DS RHE OS HDs, ref. BCR 01142 • 6 NFS Storage Array HDs			
Tasks Summary: MMCR repair Annual calibration Routine maintenance	Safety: Major Hazards: Caustic chemicals (KOH), Explosive gas (H2), AC electricity Hazard Controls: BOM Electrolyser Handbook, BM Electrolyser Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV Electrical Installations, 2-man rule			
	When replacing items (e.g., desiccant, filters, etc.), record and report the quantity of spares left on site.			
SITE TASKS				

	High priority / u	usually non-routine	Low p	riority / usually routine	Completed	
Priority	System	Date Completed (dd/Month)	Service Time (hours)	For each priority item ins	Tasks sert new line (row) for each date/time entry	
1	MMCR			Replace switches w/ those		
		13-Oct	3	Switches replaced on Mar	nus MMCR	
2	SMET (WND)			Replace upper anemomet		
		14-Oct	2	Upper Anemometer replac	ced, replacement form sent to L.Jones	
2	MWR			Check MWR operation - c		
		12-Oct	5	Investigations found comp board	nunications failure on MWR digital circuit	
3	DS			Install 2 upgrade RHE OS	HDs - ref. BCR 01142	
		21-Oct	2	Installed upgrade RHE HD	Os as per BCR 01142	
3	DS			Install new RAID collector w/ 2 RHE OS HDs		
		13-Oct		1 Installed collector awaiting further instructions from Ron Reed		
		14-Oct		1 Collector computer powered on From: Ronald Reed [mailto:rreed@ops.sgp.arm.gov] Sent: Saturday, 14 October 2006 5:45 AM To: Troy Culgan Subject: Re: Manus Collector I have turned the power back on at the APC Switch and told the machine to power up, but I am not getting anything. Power it up as soon as you can. Ron		
		15-Oct	0.5	5 Ron Reed completed checks and upgrades		
3	DS	24.0		Upgrade NFS Storage Array HDs		
	LICOEN	21-Oct	0.1	1 Upgrade to be done at a later date (SV-0702M)		
4	H2GEN	14-Oct		Repair HOGEN with spare on site (Glowacki) 2 Commenced investigations into equipment repair/ water management solutions.		
		16-Oct		3 Work progressing on water management solution		
		17-Oct		Work progressing on water		
		18-Oct	8	Water treatment plant repaired water pump replaced, Hogen still to be tested		
		l		10 00 10100		

	SITE TASKS						
High priority / usually non-routine Low p		Low p	priority / usually routine Completed				
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry			
		19-Oct		Check and start HOGEN. Hogen producing gas.			
		22-Oct	4	Verify operation, HOGEN operational			
5	TSI			Change out mirror			
		13-Oct	1	Mirror replaced			
5	TSI			Check board for heat sinks			
		13-Oct	1	Heat sinks installed			
5	TSI			Troubleshoot shadow band			
		13-Oct	5	Progressing with investigation into control board communications			
				errors, fault currently appears intermittent.			
	-	24-Oct	2	TSI packed for shipment to Darwin			
6	CAL			Record configurations before starting calibration			
_		12-Oct	0.5	Loggernet configuration recorded			
6	LGR			CAL - Verify quantity and serial numbers of spare loggers			
		14-Oct	1	One Spare data logger serial number:5968			
7	PSP-G (SKY)			CAL - Replace SKYRAD PSP (existing spare to remain on site)			
		12-Oct	1	SKYRAD PSP replaced			
7	BW-D (SKY)			CAL - Replace SKYRAD B&W			
		12-Oct	1	SKYRAD B&W replaced			
7	NIP (SKY)			CAL - Replace NIP			
		12-Oct	1	NIP replaced			
7	PSP (GND)			CAL - Replace GNDRAD PSP			
		12-Oct	1	GNDRAD PSP replaced			
7	TRH (SMET)			CAL - Compare T/RH sensor			
		22-Oct	2	Comparison complete			
7	WND (SMET)			CAL - Compare anemometers			
		14-Oct	2	Anemometer cal complete - upper wind anemometer changed ou			
				due to poor bearing performance			
7	ORG (SMET)	-		CAL - Compare ORG			
	(2	22-Oct	1	1 Checks performed using ORG test set			
7	IRT (SKY)			CAL - Compare SKYRAD IRT			
_	IDT (OND)	15-Oct	1	SKYRAD IRT check complete			
7	IRT (GND)	15.0		CAL - Compare GNDRAD IRT			
	OFIL	15-Oct	1	GNDRAD IRT cal check complete			
7	CEIL	10.0		CAL - Calibrate Ceilometer - Tip and aim at trees			
		16-Oct	1	Calibration check complete, calibration Check form sent to			
_	CAL			L.Jones			
7	CAL	40.034	^	CAL - Perform RSU check			
7	AMC	12-Oct	2	RSU check complete, results sent to L.Jones			
7	AWS	47.0	4	CAL - Calibration check as per BOM procedure			
0	CAL	17-Oct	1	1 Stevenson screen repair			
8	CAL	12.0=	4	Record new configurations and send them to Larry Jones			
0	CAL	12-Oct	1	New loggernet configurations recorded and sent to L.Jones			
O	OAL			Fill out calibration/replacement records and send them to Larry			
		12-Oct	1	Jones			
		12-Oct		1 Instrument replacement forms completed and sent to L.Jones 1 Upper anemometer instrument replacement form sent to L.Jones			
		14-001	ı	Topper anemometer instrument replacement form sent to £.30nes			
8	OTHER			Complete Audit-out form send it to Larry Jones			
	• · · · · · · ·	24-Oct	1	Completed, form sent to L Jones			
g	TBRG	24 000	<u>'</u>	Connect AWS TBRG to SMET data logger			
J	Common Time to the data logger						

	SITE TASKS					
	High priority / u	sually non-routine	Low p	oriority / usually routine Completed		
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry		
		15-Oct		In Progress		
		16-Oct	2	Complete		
9	GPS Suominet			Change out Metpack (sent from Darwin 28Jul06)		
		15-Oct		In Progress		
		16-Oct	2	Completed reference:		
				Facility Contact WorkSheet (CS-2006-0970)		
9	H2GEN			Electrolyser maintenance (Culgan)		
		19-Oct		In Progress		
		23-Oct		Repair water leak balloon launcher		
		23-Oct	2	Complete		
10	BBSS			Retrieve sonde data from 23Sep through 02 Oct, if possible		
		20-Oct	1	Raw Sonde data retrieved from R1, data to be verified and		
				ingested.		
10	OTHER			Clean excessed laptop HDs		
		16-Oct	3	Completed		
11	HVAC			Pressure-wash coils on exterior units		
		24-Oct	2	Completed		
11	GENSET			Check 12-V batteries with Hydrometer		
		21-Oct		Nil Hydrometer on site - to be completed at a later date (SV-		
				0702M)		
11	GENSET			Assess fuel tanks for painting		
		15-Oct	0.5	Fuel tanks do not require painting		
11	ALL SYSTEMS			Perform routine maintenance as outlined in Maintenance Checklist - Send completed checklist to Monty Apple		
		19-Oct		In Progress		
		24-Oct	3	Completed checklist sent to M. Apple		
11	ESH			Put laser caution labels on MPL		
		21-Oct	0.5	Caution Labels in place		
11	ESH			Install new fire extinguisher brackets (1 for D-Van, 1 for I-Van)		
		23-Oct	2	2 I van Bracket installed, John Glowacki to submit survey report of fire extinguisher condition.		
11	ESH			Install fire extinguisher tags to indicate when checks are		
				performed		
		23-Oct	1	Tags installed		
11	ESH			Check Eyewash station		
		15-Oct	1	Eyewash solution changed out in eyewash station, U Van eyewash		
				bottle replaced		
11	BBSS			Change out Velcro strap sonde retainer		
		21-Oct	0.5	5 completed		
11	MMCR			Change out antenna heater filters		
		13-Oct	1	1 Heater filter changed during MMCR switch change		
11	MMCR			Change out fan for Radian Receiver, 12 VDC		
		13-Oct	1	1 Fan checked during MMCR switch change		
11	MMCR			Change out TWTA desiccant		
		13-Oct	1	Desiccant changed during routine maintenance and switch change		
11	MPL			Change out shutter timer batteries (AA)		
		18-Oct	0.5	5 Shutter timer batteries replaced		
11	MWR			Check Teflon window		
		16-Oct	1.5	Teflon window replaced		

	SITE TASKS					
	High priority / usually non-routine Low p		riority / usually routine	Completed		
Priority	System	Date Completed (dd/Month)	Service Time (hours)			
11	SMET			Change out T/RH aspirat	or fan	
		18-Oct	1	aspirator fan replaced		
11	COMM			Check antenna and conn	ections on Nera phone	
		19-Oct	1	Complete, antenna and c	connection in good condition	
11	COMM			Check Iridium phone and	charge it if necessary	
		14-Oct	1	Communication check co	mplete, Charging complete	
11	SKYRAD			Check tracker for alignme	ent	
		19-Oct	1	Replace communication I	ead connector	
		20-Oct	1	Adjust time on tracker by	2 min, Adjust sun sensor position, will	
				continue to monitor tracke	er alignment	
		24-Oct	2		g tracker appears to fully aligned	
11	DS			Change out BIOS batterie	es in collector and NFS server, and then	
				reset BIOS		
		14-Oct	0		Nil replacement batteries on site - to be completed at a later date	
				(SV-0702M)		
11	OTHER			Check operation of Observer computer		
		17-Oct	2	Observer computer checked with some observer training in		
				computer skills		
11	OTHER			Replace Fluro lamps Balloon shed		
		19-Oct	2	Replaced Fluro lamps in balloon shed with observer assistance.		
12	OTHER			Retrieve property tags on unused computers and send them back to PNNL (attn: Jane McKinney)		
		16-Oct	3	Property tags retrieved and report sent to L.Jones		
12	OTHER			Install ARM Education Kiosk - Location TBD		
		24-Oct		No instructions received - to be completed at a later date (SV-0702M)		
12	OTHER			Remove WD property tag (WD22311) from IBM 380XD laptop and		
				send it to J. McKinney at PNNL - Make sure HD has no		
				information prior to removal of tags		
		16-Oct	0.5	Property tag retrieved		
12	OTHER			Assist Nauru in Skrad logger problem		
		17-Oct	2	Worked with Franklin at N	Nauru to resolve Skyrad logger problems	
		18-Oct	1	Continued work to resolve SKYRAD logger problem, conclusion		
				was faulty IRT causing inconsistencies in logger readings on other		
				channels.		

SITE TASKS						
	High priority / usually non-routine		Low priority / usually routine Completed		Completed	
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry		
		20-Oct	1	Facility Contact WorkSheet (CS-2006-0989) Facility Contacted: Nauru Contact Date: 20-Oct-2006 Contact Time: 23:20:00 UTC Contact Sheet Initiator: Culgan, Troy Person or System Contacted: Teimitsi, Franklin System(s) Related to Contact: IRT		
				Contact Subject/Keywords: SKYRAD IRT faulty Contact Details: I had Franklin connect the IRT as per mentors request, the connection of IRT had the immediate affect of increaseing all instrument readings and the internal logger sensors of Battery Vdc and CR23Temp displayed -INF. When IRT disconnected all measurements return to normal. Status: IRT disconnected.		
13	SHIPPING	-		List items to be shipped following visit		
	Packed	22-Oct		Ship Cal kit to Nauru		
	Packed	23-Oct		Ship replaced radiometer		
	Packed	24-Oct		Ship replaced anemomet		
	Packed	23-Oct		Ship unserviceable DS computer		
	Packed	24-Oct	2	Ship TSI to Darwin for repair (plus upgrade to GX620 computer)		
14	FUTURE NEEDS			List items needed for future visits (spares, etc.) - to be completed on SV-0702M Tool kit update		
				spares kit for on site lawn mower (blades, spark plugs, air filter, oil, gasket kit, pullcord, etc) Brushcutter plus spares kit and safety equipment for use(site		
				currently kept in trim by hand) T/RH aspirator fan		
				Lamp Philips TLX XL 40W/33 (order code:261373) qty 6		
				Genset Hydrometer		
				Timer/stopwatch for balloon launches		
				60 Sec timer electrolyser		
<u> </u>			Electrolyser Hydrometer			
			HOGEN gas sensor calibration gas			
				Consider install of Liebert UPS in E-Van for future BBSS install		
			Chuck Dewalt Drill DW953			
			Blank Media (CD-R, DVD, Floppies)			
			240 Volt charger Dewalt (7.2 - 18V)			